



EVA Drivers 6.1 and TWAIN Installation Guide for EVA Classic Digital Sensors

Note: This guide is relevant only to customers looking to connect an EVA Classic digital sensor to dental imaging software other than EVAsoft (i.e., Prolmage or other third party software)

The EVA Drivers 6.1 will work on these operating systems ONLY:

- Windows XP 32-bit
- Windows Vista 32-bit
- Windows 7 32-bit and 64-bit
- Windows 8 32-bit and 64-bit (NOTE: Prolmage software is NOT supported for Windows 8)

It is very important to follow the correct order when installing the new drivers.

For Prolmage users, always install Prolmage digital imaging software first and then install the EVA drivers 6.1. This is due to the fact that previous versions of Prolmage also install drivers and can overwrite the correct files. If at any time you re-install Prolmage, always re-install the EVA drivers 6.1 as well. It is not necessary to upgrade or re-install Prolmage when upgrading the EVA drivers. The new EVA drivers 6.1 are backward compatible and will function correctly with previous versions of Prolmage.

Table of Contents:

New Installations of the EVA Drivers 6.1.....	Page 2
Upgrading the EVA Drivers.....	Page 7
EVA TWAIN Installation.....	Page 8
Using the EVA TWAIN Application.....	Page 14


New Installations of the EVA Drivers 6.1

Follow these steps after you have installed ProImage or a software package other than EVASoft that you will be using to capture x-rays with an EVA Classic sensor.

1. On Window XP, please login to the computer as the Administrator
On Windows Vista, please turn off the “User Account Control”
On Windows 7 or 8, please lower the User Account Control settings to “Never Notify”
2. Disconnect all EVA sensors
3. Insert the USB Hardware and TWAIN Drivers Installation CD
4. The following “Welcome Screen” dialog will open




5. Click on the “Install EVA Drivers” button
6. The following “Device Driver Installation Wizard” window will open



7. Click Next
8. If the following window opens, click “Continue Anyway”



9. The following window will then appear:




10. Click “Finish”
11. Connect the EVA sensor to the USB port on the computer
12. If the “Found New Hardware Wizard” does NOT appear, skip to step 20

13. If the “Found New Hardware Wizard” opens, follow these steps:




14. Select “No, not this time” and click “Next”



15. Click “Next”



16. Choose "Continue Anyway"




17. When finished, the following message will appear:



18. Click “Finish” to complete the installation

19. If prompted to restart the computer, select “Restart now”

20. Verify that a message is displayed stating that the device was installed properly, and is ready to use



Example of Windows 7 message

21. Open ProImage or other software package

22. Capture test x-rays

Upgrading the EVA Drivers

On a PC with the previous version of the EVA drivers installed, follow the steps below:

1. On Window XP, please login to the computer as the Administrator
On Windows Vista, please turn off the “User Account Control”
On Windows 7 or 8, please lower the User Account Control settings to “Never Notify”
2. Disconnect all EVA sensors
3. First start by un-installing the OLD version of the EVA drivers:
 - a. Insert the USB Hardware and TWAIN Drivers Installation CD for the OLD version of the drivers
 - b. Select “Remove” from the Install Wizard
 - c. Restart the computer
4. Secondly, install the EVA Drivers version 6.1:
 - d. Insert the NEW USB Hardware and TWAIN Drivers Installation CD version 6.1
 - e. Follow the directions for New Installations of the EVA Drivers 6.1 beginning on Page 2


EVA TWAIN Installation

Follow these steps to install both the EVA Drivers and the EVA TWAIN Drivers:

1. Insert the USB Hardware and TWAIN Drivers Installation CD
2. The following “Welcome Screen” dialog will open




3. Click on the “Install EVA TWAIN” button
4. The following “Device Driver Installation Wizard” window will open



5. Click Next
6. If the following window opens, click “Continue Anyway”




7. The following window will then appear:




8. Click “Finish”


9. The following window will then open automatically




10. Click "Next"




11. Enter you user information and click "Next"



12. Click “Next”




13. Click “Install”



14. Click "Finish"




15. Select a language and click "Save Settings"



16. Click "OK" to restart the computer


17. The following message may appear when the computer restarts, click OK




18. Connect the EVA sensor to the USB port on the computer


19. If the “Found New Hardware Wizard” opens, please go to step 13, on Page 4

20. Verify that a message is displayed stating that the device was installed properly, and is ready to use



Example of Windows 7 message




21. Right-click on the  icon in your system tray (lower right-hand corner of the screen). Select “Activate Sensor”

22. Verify that the icon changes to: 


23. You are now ready to capture x-rays

Using the EVA TWAIN Application

General Use:

- A Small EVA TWAIN icon will appear in the system tray at the bottom of the screen
- If the EVA sensor is not connected to the computer, the following EVA TWAIN icon will appear: 
- To proceed, plug the EVA sensor to the USB port of the computer, right click on the EVA TWAIN icon and choose “Activate Sensor”. Then, the EVA TWAIN icon will be replaced by: 
- In case an error occurs while EVA is connected, the following icon will appear: 

Capturing Images:

- When capturing images with the EVA sensor, the following “EVA Images” blinking icon will also appear in the system tray (in addition to the EVA TWAIN icon): 
- Left click on the “EVA Images” icon in order to view the captured images. All the captured images will appear in a viewing window. As new images are being captured, they will be added continuously in this window

Please note the following system limitation: The EVA TWAIN software will only keep up to 64 images in memory. It is recommended that the images be downloaded to the main imaging application after each patient’s full x-ray session.

Please also note that directions for using the TWAIN device from a software application other than ProImage or EVASoft should be provided from that software application manufacturer. In most cases, there is an option to import images from the TWAIN devices available on the system.

Disconnecting EVA: If you wish to disconnect the EVA sensor, left click on the EVA TWAIN icon and choose “Remove Sensor”. Then, unplug the EVA sensor.

Reconnecting EVA: If you wish to reconnect the EVA sensor, plug the EVA sensor into the computer via the USB port. Wait until the green light shows up in the EVA sensor docking station. Then, right click on the EVA TWAIN icon and choose “Activate Sensor”.

Reconnecting after a sudden disconnect: If an EVA sensor has been disconnected and reconnected without clicking on “Remove Sensor” first, please left click on the EVA TWAIN icon and choose “Remove Sensor”. Unplug the EVA sensor. Plug the EVA sensor back in and wait until the green light shows up in the EVA sensor docking station. Then, right click on the EVA TWAIN icon and choose “Activate Sensor”.